


Return of empty
yarn packaging
(cops H9)



heigh - 446mm



diameter - 203mm





SOP : Standard Operating Procedure

Title:	H9 Bobbins Arrangement in cardboard boxes	Code	SOP-LC-005	No.Rev.	1
Area	Customers	Department	Logistics	Date	8/3/2020

1



Lay a wooden pallet on the floor

2




Assemble the cardboard base and place it on the

3



Assemble the cardboard body and place it inside the base, as shown in the image.

4



Arrange 20 H9 bobbins inside the box. As shown in the picture

5




Weave the next row by arranging perpendicular 4 bobbins in each corner, fill the row with bobbins in the middle.

6



Repeat steps 4 and 5, until the box is full, arrange the bobbins 8-9 rows high inside the box.
Each box must contain approximately 150-180 Bobbins



TOTAL pallets 1200x1000
for H5 21pc / pack
diameter pack - 1200x1100x2100mm

IMPORTANT!



Please do not cut remaining yarn and leave rest of yarn on spools.



Please follow previous filling instructions.
Do not mix different types of spools
in one box. Better send incomplete boxes.



Do not collect empty cardboard packaging.
Empty cardboards use only for returning bobbins and separators.



Put a wooden pallet under each box.



- fill box only up to the edge
- close the big box with the original bottom cover
- store all boxes dry